

Timing chain: The timing chain was never fitted with any means of tensioning, this causes a rattle when worn, a timing chain tensioner, part/no 461256S is available from club spares and this keeps tension on the chain throughout its life and prevents rattling.